#### Work Order ID 68466

Page 1

Wednesday, April 13, 2011 4:15:08 PM

Item ID:

D3443-043

Accept



Setup Start

Stop



**Revision ID:** 

Item Name:

Strut Weldment Assembly

**Start Date:** 

4/13/2011

Start Qty: 5.00

Req'd Qty: 5.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Required Date: 4/20/2011

**Process Plan:** 

QC:

Date://-04-1

Date:

Tooling:

Date:

Date:\_

Run

Start



Stop

Sequence ID/ Work Center ID **Draw Nbr** 

Operation Description

**Revision Nbr** 

Set Up/ **Run Hours** 

SPC (Y/N):

**Tool ID** 

Tool # Plan Code

Reject Accept Qty Qty

Reject Number

Insp. Stamp

D3443

Rev C

100

Large Fab

Large Fab

Large Fab

Memo

0.00

0.00

EZ 11-5-18



110

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

Weld assembly as per dwg D3443

0.00

Memo

0.00

120

QC

QC5- Inspect part completeness to step on W/O

0.00

rstrain 2000

Memo

Quality Control

Dart A	\erospac	e Ltd
--------	----------	-------

Dart Aei	ospace	LIG								`
W/O:				W	ORK ORDER CHANGES					
DATE	STEP	PRO	CEDUR	E CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
Part No	•	PAR #:	Faul	t Cat	egory:N	ICR: Yes	No <b>DQ</b>	A:	Date: _	<u> </u>
		esolution:	Disp	ositi	on: C	A: N/C C	losed:			
NCR:		<b>V</b>	VORK	ORI	DER NON-CONFORMANO	CE (NC	R)			
DATE	STEP	Description of NC			Corrective Action Section B		Verifi	cation	Approval	Approval
DAIL	SIEF	Section A	Initi Chief I		Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector
										į
										1
	, ,				•					
					\$	-	Ī			

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

### Work Order ID 68466

Wednesday, April 13, 2011 4:15:08 PM



Page 2

Item 1D:

D3443-043

Accept



Setup Start



**Revision ID:** 

Item Name:

Required Date: 4/20/2011

**Start Date:** 

4/13/2011

Start Qty: 5.00

Req'd Qty: 5.00



**Cust Item ID:** 

**Customer:** 

**Tool ID** 

Reference:

Approvals:

Process Plan:

Date:

**Tooling:** SPC (Y/N): Date:

Date:

Tool # Plan

Code

Reject

Qty



Insp.

Stamp

Sequence ID/

Work Center ID

Powdercoat

Powder Coating

Operation **Description** 

QC:

White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel

Set Up/ **Run Hours** 

0.00

0.00

M116 964 Mask holes as per dwg D3443 | START TIME:
OVEN TEMPERATURE:

DEFINISH
ME:

140

Quality Control

QC3- Inspect Part Finish

0.00

Memo

0.00

150

Packaging Packaging

0.00

0.00

116/245/

Memo

Identify as per dwg & Stock Location

Strut Weldment Assembly

Date:

Run

Accept

Qty

Start

Stop

Reject

Number

Stop

130

Dart Aerospace I	Ltd
------------------	-----

W/O:					ORK ORDER CHANGE	ES					
DATE	STEP	PRO	CEDURE	CH/	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										· ·	
							- - - - -				
Part No	:	PAR #:	Fault	Cate	egory:	NCR	: Yes N	lo <b>DQ</b> /	<b>\</b> :	Date:	
	R	esolution:								Date:	
NCR:	,	V	VORK (	RD	DER NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC Section A	Initia Chief E		Corrective Action Section Action Description Chief Eng	on B	Sign & Date	Verific Secti		Approval Chief Eng	Approval QC Inspector
			Office E	'g	· ·		Duto				
1											
								ļ			
											S

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE

### Work Order ID 68466

Page 3

Item ID:

Wednesday, April 13, 2011 4:15:09 PM

Accept

Setup Start

**Revision ID:** Item Name:

Strut Weldment Assembly

Stop

**Start Date:** 

4/13/2011

D3443-043

Start Oty: 5.00 Req'd Qty: 5.00

**Cust Item ID:** 

**Customer:** 

Reference:

QC:

Date:

Tooling:

Date:

Start

Approvals:

Required Date: 4/20/2011

Process Plan:

Operation

Description

Date:\_\_\_\_\_

SPC (Y/N):

Date: \_\_\_\_

Stop

Sequence ID/

**Work Center ID** 

QC21- Final Inspection - Work Order Release

Set Up/ **Run Hours** 

**Tool ID** 

Tool # Plan Code Reject Qty

Run

Accept

Qty

Reject Insp. Number

Stamp

Memo

0.00

Quality Control

0.00

MF 25-25

Dar	t Aeı	rosp	ace	Ltd
-----	-------	------	-----	-----

W/O:				WOR	K ORDER CHANG	SES					
DATE	STEP	PROC	EDURE	CHANG	E		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		÷									* A *
Part No	•	PAR #:	_ Fault	Categor	y:	_ NCR	: Yes N	lo <b>DQ</b>	<b>4</b> :	_ Date: _	
	R	esolution:	_ Dispo	sition: _		QA:	N/C Clo	sed:		Date: _	
NCR:		W	ORK (	RDER	NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initia	i	Action Description	tion B	Sign &	Verific Secti	cation on C	Approval Chief Eng	Approval QC Inspector
			Chief E	ng	Chief Eng		Date			-	
									į		

## **Picklist Print**

Wednesday, April 13, 2011 4:15:14 PM

Work Order ID: 68466

Parent Item: D3443-043

Parent Item Name: Strut Weldment Assembly

**Start Date:** 4/13/2011

Required Date: 4/20/2011

Page 1

**(**.

Start Qty: 5.00 Required Qty: 5.00

Comments:

IPP REV. A 05.11.17


**NEW ISSUE** 

EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3443-3		Manufactured	No			100	Each	2.0000	1	5 <i>Q</i>	11-57	18	
·	6	9055x	3	Location WA023	58560)	Loc	Oty 2 2	Loc Code		7	-		
D3443-7 		Manufactured	No			100	Each	4.0000		5 LL	11-5	78	
		69056x	1	WA023	58561	Loc	<u>Oty</u> 4 4	Loc Code	_	4	-		
D3966-4-750		Manufactured	No			100	Each	55.0000	1 	5 <u> 2</u>	11-5	18	
				Location ST100	(58711)	Loc	Oty 55 55	Loc Code	_		_		


Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:				WORK ORDER CH					
DATE	STEP	PRO	CEDURE	CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							1		
Part No:	·	PAR #:	Fault	Category:	NCR	: Yes N	o DQA:	Date: _	
	R	esolution:						Date: _	
NCR:		V	WORK (	RDER NON-CONF	ORMANCE	(NCR)			
				Corrective Action	Section B		I	Ī	1
DATE	STEP	Description of NC		1		Sian &	Verification		Approval
DATE	STEP	Description of NC Section A	Initia Chief E	Action Descr	iption	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				
DATE	STEP			Action Descr	iption				



## **Dart Aerospace Ltd**

W/O:			!	WORK ORDER	CHANGES				
DATE	STEP	PRO	OCEDURE	CHANGE	В	y I	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							•		
,							1		
Part No	:	PAR #:	Fault (	Category:	NCR: \	es No	DQA:	Date:	
	R	esolution:	Dispos	sition:	QA: N/	C Clos	ed:	Date: _	
NCR:			WORK O	RDER NON-CON	IFORMANCE (N	ICR)			
DATE	STEP	Description of NC Section A	Initial	Corrective Actio	cription Si	gn &	Verification Section C	Approval Chief Eng	Approval QC Inspector
		Coolient	Chief Eng	Chief E	ing [	Date	000,1011		
						:			
									,
					į.		,		




# **Dart Aerospace Ltd**

W/O:		3.00		WORK ORDER C	HANGES			·	
DATE	STEP	PROG	CEDURE	CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									ı
<u></u>									
Part No	:	PAR #:	_ Fault	Category:	NCR	l: Yes N	o DQA:	Date:	
	R	esolution:						Date: _	
NCR:		W	ORK (	RDER NON-CONF	ORMANCE	(NCR)	• • • • • • • • • • • • • • • • • • • •		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
DATE	STEP	Description of NC	Im itia	Corrective Action	Section B	Sign &	Verification		Approval
		Section A	Initia Chief E		iption	Date	Section C	Chief Eng	QC Inspector
*****									
							:		


NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



# **Dart Aerospace Ltd**

W/O:				<b>WORK ORDER</b>	CHANGES				
DATE	STEP	PRO	CEDURE	CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,							
								3 4 5	
Part No	:	PAR #:	Fault	Category:	NCR	: Yes No	DQA:	Date: _	1
	R	esolution:					ed:	Date: _	
NCR:		V	VORK O	RDER NON-COI	NFORMANCE	(NCR)			
DATE	STEP	Description of NC	Initia	Corrective Action De		Sign &	Verification	Approval	Approval
		Section A	Chief En	g Chief		Date	Section C	Chief Eng	QC Inspector
						:			
				į					



Dart A	<b>Aeros</b>	pace	Ltd
--------	--------------	------	-----

W/O:				WORK ORDER	CHANGES				
DATE STEP		PROCEDURE		CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		*	,						
		1							
			·						
Part No: PAR #:			1		NCR: Yes No DQA:				
		Disp	sition:	QA: N/C	_ QA: N/C Closed:			Date:	
NCR:			WORK (		NFORMANCE (NO	CR)			
DATE	STEP	Description of NC Section A	initia Chief E	Corrective Act Action Do	ion Section B escription Sign f Eng Da			Approvai Chief Eng	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·		4		Ing Chie	reng Da	le			
•									
		₹ s.							